

ELEC0029 - Electric Power System Analysis

The synchronous machine (detailed model)

Thierry Van Cutsem
t.vancutsem@ulg.ac.be www.montefiore.ulg.ac.be/~vct

..vancutsemedig.ac.be www.monterlore.dig.ac.be/ vc

February 2020

Objectives


Extend the model of the synchronous machine considered in course ELEC0014:

- more detailed
- appropriate for dynamic studies
- includes the effect of damper windings
- applicable to machines with salient-pole rotors (hydro power plants)

Relies on the Park transformation, also used for other power system components.

The two types of synchronous machines

Round-rotor generators (or turbo-alternators)




- Driven by steam or gas turbines, which rotate at high speed
- one pair of poles (conventional thermal units)
 or two (nuclear units)
- cylindrical rotor made up of solid steel forging
- diameter << length (centrifugal force !)
- field winding made up of conductors distributed on the rotor, in milled slots
- even if the generator efficiency is around 99 %, the heat produced by Joule losses has to be evacuated!

Large generators are cooled by hydrogen (heat evacuation 7 times better than air) or water (12 times better) flowing in the hollow stator conductors.




Salient-pole generators



- Driven by hydraulic turbines (or diesel engines), which rotate at low speed
- many pairs of poles (at least 4) ⇒ it is more convenient to have field windings concentrated and placed on the poles
- air gap is not constant: min. in front of a pole, max. in between two poles
- poles are shaped to also minimize space harmonics
- diameter >> length (to have space for the many poles)
- rotor is laminated (poles easier to construct)
- generators usually cooled by the flow of air around the rotor.







Damper windings and eddy currents in rotor

Damper windings (or amortisseur)

- round-rotor machines: copper/brass bars placed in the same slots at the field winding, and interconnected to form a damper cage (similar to the squirrel cage of an induction motor)
- salient-pole machines: copper/brass rods embedded in the poles and connected at their ends to rings or segments.


Why?

- in perfect steady state: the magnetic fields produced by both the stator and the rotor are fixed relative to the rotor \Rightarrow no current induced in dampers
- after a disturbance: the rotor moves with respect to stator magnetic field \Rightarrow currents are induced in the dampers...
 - ... which, according to Lenz's law, create a damping torque helping the rotor to align on the stator magnetic field.

Eddy currents in the rotor

Round-rotor generators: the solid rotor offers a path for eddy currents, which produce an effect similar to those of amortisseurs.

Modelling of machine with magnetically coupled circuits



Number of rotor windings = degree of sophistication of model. But:

- more detailed model ⇒ more data are needed
- while measurement devices can be connected only to the field winding.

Most widely used model: 3 or 4 rotor windings:


- f: field winding d_1, q_1 : amortisseurs
- q_2 : accounts for eddy currents in rotor; not used in (laminated) salient-pole generators.

Remarks

In the sequel, we consider:

- a machine with a single pair of poles, for simplicity.
 This does not affect the <u>electrical</u> behaviour of the generator (it affects the moment of inertia and the kinetic energy of rotating masses)
- the general case of a salient-pole machine.
 For a round-rotor machine: set some parameters to the same value in the d and q axes (to account for the equal air gap width)
- the configuration with four rotor windings (f, d_1, q_1, q_2) . For a salient-pole generator : remove the q_2 winding.

Relations between voltages, currents and magnetic fluxes



Stator windings: generator convention:

$$v_a(t) = -R_a i_a(t) - \frac{d\psi_a}{dt} \qquad v_b(t) = -R_a i_b(t) - \frac{d\psi_b}{dt} \qquad v_c(t) = -R_a i_c(t) - \frac{d\psi_c}{dt}$$

In matrix form:

$$\mathbf{v}_T = -\mathbf{R}_T \mathbf{i}_T - \frac{d}{dt} \psi_T$$
 with $\mathbf{R}_T = \operatorname{diag}(R_a R_a R_a)$

Rotor windings: motor convention:

$$v_f(t) = R_f i_f(t) + \frac{d\psi_f}{dt}$$

$$0 = R_{d1} i_{d1}(t) + \frac{d\psi_{d1}}{dt}$$

$$0 = R_{q1} i_{q1}(t) + \frac{d\psi_{q1}}{dt}$$

$$0 = R_{q2} i_{q2}(t) + \frac{d\psi_{q2}}{dt}$$

In matrix form:


$$\mathbf{v}_r = \mathbf{R}_r \mathbf{i}_r + \frac{d}{dt} \psi_r$$
 with $\mathbf{R}_r = \operatorname{diag}(R_f R_{d_1} R_{q_1} R_{q_2})$

Inductances

Saturation being neglected, the fluxes vary linearly with the currents according to:

$$\left[\begin{array}{c} \psi_T \\ \psi_r \end{array}\right] = \left[\begin{array}{cc} \boldsymbol{L}_{TT}(\theta_r) & \boldsymbol{L}_{Tr}(\theta_r) \\ \boldsymbol{L}_{Tr}^T(\theta_r) & \boldsymbol{L}_{rr} \end{array}\right] \left[\begin{array}{c} \boldsymbol{i}_T \\ \boldsymbol{i}_r \end{array}\right]$$


- L_{TT} and L_{Tr} vary with the position θ_r of the rotor
- but L_{rr} does not
- the components of L_{TT} and L_{Tr} are periodic functions of θ_r obviously
- the space harmonics in θ_r are assumed negligible = sinusoidal machine assumption.



$$\mathbf{L}_{TT}(\theta_r) =$$

$$\left[\begin{array}{ccc} L_0 + L_1 \cos 2\theta_r & -L_m - L_1 \cos 2(\theta_r + \frac{\pi}{6}) & -L_m - L_1 \cos 2(\theta_r - \frac{\pi}{6}) \\ -L_m - L_1 \cos 2(\theta_r + \frac{\pi}{6}) & L_0 + L_1 \cos 2(\theta_r - \frac{2\pi}{3}) & -L_m - L_1 \cos 2(\theta_r + \frac{\pi}{2}) \\ -L_m - L_1 \cos 2(\theta_r - \frac{\pi}{6}) & -L_m - L_1 \cos 2(\theta_r + \frac{\pi}{2}) & L_0 + L_1 \cos 2(\theta_r + \frac{2\pi}{3}) \end{array} \right]$$


$$L_o, L_1, L_m > 0$$



$$\mathbf{L}_{Tr}(\theta_r) =$$

$$\left[\begin{array}{cccc} L_{af}\cos\theta_{r} & L_{ad1}\cos\theta_{r} & L_{aq1}\sin\theta_{r} & L_{aq2}\sin\theta_{r} \\ L_{af}\cos(\theta_{r}-\frac{2\pi}{3}) & L_{ad1}\cos(\theta_{r}-\frac{2\pi}{3}) & L_{aq1}\sin(\theta_{r}-\frac{2\pi}{3}) & L_{aq2}\sin(\theta_{r}-\frac{2\pi}{3}) \\ L_{af}\cos(\theta_{r}+\frac{2\pi}{3}) & L_{ad1}\cos(\theta_{r}+\frac{2\pi}{3}) & L_{aq1}\sin(\theta_{r}+\frac{2\pi}{3}) & L_{aq2}\sin(\theta_{r}+\frac{2\pi}{3}) \end{array} \right]$$

$$L_{af}, L_{ad1}, L_{aq1}, L_{aq2} > 0$$



$$\mathbf{L}_{rr} = \left[\begin{array}{cccc} L_{ff} & L_{fd1} & 0 & 0 \\ L_{fd1} & L_{d1d1} & 0 & 0 \\ 0 & 0 & L_{q1q1} & L_{q1q2} \\ 0 & 0 & L_{q1q2} & L_{q2q2} \end{array} \right]$$

Park transformation and equations

Park transformation

is applied to stator variables (denoted $._T$) to obtain the corresponding Park variables (denoted $._P$):

$$\begin{array}{rcl} \mathbf{v}_P & = & \mathcal{P} \; \mathbf{v}_T \\ \mathbf{\psi}_P & = & \mathcal{P} \; \mathbf{\psi}_T \\ & \quad \mathbf{i}_P & = & \mathcal{P} \; \mathbf{i}_T \\ \end{array}$$
 where
$$\begin{array}{rcl} \mathcal{P} & = & \sqrt{\frac{2}{3}} \left[\begin{array}{ccc} \cos\theta_r & \cos(\theta_r - \frac{2\pi}{3}) & \cos(\theta_r + \frac{2\pi}{3}) \\ \sin\theta_r & \sin(\theta_r - \frac{2\pi}{3}) & \sin(\theta_r + \frac{2\pi}{3}) \\ \frac{1}{\sqrt{2}} & \frac{1}{\sqrt{2}} & \frac{1}{\sqrt{2}} \end{array} \right]$$

$$egin{array}{lll} oldsymbol{v}_P &=& \left[egin{array}{lll} v_d & v_q & v_o \end{array}
ight]^T \ oldsymbol{\psi}_P &=& \left[egin{array}{lll} \psi_d & \psi_q & \psi_o \end{array}
ight]^T \ oldsymbol{i}_P &=& \left[egin{array}{lll} i_d & i_q & i_o \end{array}
ight]^T \end{array}$$


It is easily shown that:

$$\mathcal{P} \, \mathcal{P}^T = \mathbf{I} \quad \Leftrightarrow \quad \mathcal{P}^{-1} = \mathcal{P}^T$$

Interpretation

Total magnetic field created by the currents i_a , i_b et i_c :

projected on
$$d$$
 axis: $k \left(\cos \theta_r i_a + \cos(\theta_r - \frac{2\pi}{3}) i_b + \cos(\theta_r - \frac{4\pi}{3}) i_c\right) = k\sqrt{\frac{3}{2}}i_d$
projected on q axis: $k \left(\sin \theta_r i_a + \sin(\theta_r - \frac{2\pi}{3}) i_b + \sin(\theta_r - \frac{4\pi}{3}) i_c\right) = k\sqrt{\frac{3}{2}}i_q$



The Park transformation consists of replacing the (a, b, c) stator windings by three equivalent windings (d, q, o):

- the d winding is attached to the d axis
- the q winding is attached to the q axis
- the currents i_d and i_q produce together the same magnetic field, to the multiplicative constant $\sqrt{\frac{3}{2}}$.

Park equations of the synchronous machine

$$\begin{aligned} \mathbf{v}_T &=& -\mathbf{R}_T \mathbf{i}_T - \frac{d}{dt} \psi_T \\ \mathcal{P}^{-1} \ \mathbf{v}_P &=& -R_a \mathbf{I} \ \mathcal{P}^{-1} \ \mathbf{i}_P - \frac{d}{dt} (\mathcal{P}^{-1} \ \psi_P) \\ \mathbf{v}_P &=& -R_a \mathcal{P} \mathcal{P}^{-1} \mathbf{i}_P - \mathcal{P} \left(\frac{d}{dt} \mathcal{P}^{-1} \right) \psi_P - \mathcal{P} \mathcal{P}^{-1} \frac{d}{dt} \psi_P \\ &=& -\mathbf{R}_P \ \mathbf{i}_P - \dot{\theta}_r \mathbf{P} \psi_P - \frac{d}{dt} \psi_P \\ \text{with:} \qquad \mathbf{R}_P &=& \mathbf{R}_T \quad \mathbf{P} = \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix} \end{aligned}$$

$$\text{By decomposing:} \qquad \mathbf{v}_d = -R_a \mathbf{i}_d - \dot{\theta}_r \psi_q - \frac{d\psi_d}{dt}$$

By decomposing:
$$\begin{aligned} v_d &= -R_a i_d - \dot{\theta}_r \psi_q - \frac{d \psi_d}{dt} \\ v_q &= -R_a i_q + \dot{\theta}_r \psi_d - \frac{d \psi_q}{dt} \\ v_o &= -R_a i_o - \frac{d \psi_o}{dt} \end{aligned}$$

 $\dot{\theta}_r \psi_d, \dot{\theta}_r \psi_a$: speed voltages

 $d\psi_d/dt, d\psi_a/dt$: transformer voltages

Park inductance matrix

$$\begin{bmatrix} \psi_{T} \\ \psi_{r} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{TT} & \mathbf{L}_{Tr} \\ \mathbf{L}_{Tr}^{T} & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_{T} \\ \mathbf{i}_{r} \end{bmatrix}$$

$$\begin{bmatrix} \mathcal{P}^{-1}\psi_{P} \\ \psi_{r} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{TT} & \mathbf{L}_{Tr} \\ \mathbf{L}_{Tr}^{T} & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathcal{P}^{-1}\mathbf{i}_{P} \\ \mathbf{i}_{r} \end{bmatrix}$$

$$\begin{bmatrix} \psi_{P} \\ \psi_{r} \end{bmatrix} = \begin{bmatrix} \mathcal{P}\mathbf{L}_{TT}\mathcal{P}^{-1} & \mathcal{P}\mathbf{L}_{Tr} \\ \mathbf{L}_{Tr}^{T}\mathcal{P}^{-1} & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_{P} \\ \mathbf{i}_{r} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{PP} & \mathbf{L}_{Pr} \\ \mathbf{L}_{rP} & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_{P} \\ \mathbf{i}_{r} \end{bmatrix}$$

$$\begin{bmatrix} \mathbf{L}_{PP} & \mathbf{L}_{Pr} \\ \mathbf{L}_{rP} & \mathbf{L}_{rr} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{dd} & \mathbf{L}_{df} & \mathbf{L}_{dd1} \\ \mathbf{L}_{qq} & \mathbf{L}_{qd1} & \mathbf{L}_{qq2} \\ \mathbf{L}_{oo} & \mathbf{L}_{fd1} & \mathbf{L}_{d1d1} \\ \mathbf{L}_{dd1} & \mathbf{L}_{fd1} & \mathbf{L}_{d1d1} \\ \mathbf{L}_{qq1} & \mathbf{L}_{q1q2} & \mathbf{L}_{q1q2} \end{bmatrix}$$

(zero entries have been left empty for legibility)

with:

$$L_{dd} = L_0 + L_m + \frac{3}{2}L_1$$

$$L_{qq} = L_0 + L_m - \frac{3}{2}L_1$$

$$L_{df} = \sqrt{\frac{3}{2}}L_{af}$$

$$L_{dd1} = \sqrt{\frac{3}{2}}L_{ad1}$$

$$L_{qq1} = \sqrt{\frac{3}{2}}L_{aq1}$$

$$L_{qq2} = \sqrt{\frac{3}{2}}L_{aq2}$$

$$L_{oo} = L_0 - 2L_m$$

- All components are independent of the rotor position θ_r . That was expected!
- There is no magnetic coupling between d and q axes (this was already assumed in L_{Tr} and L_{rr} : zero mutual inductances between coils with orthogonal axes).

Leaving aside the o component and grouping (d, f, d_1) , on one hand, and (q, q_1, q_2) , on the other hand:

$$\begin{bmatrix} v_{d} \\ -v_{f} \\ 0 \end{bmatrix} = -\begin{bmatrix} R_{a} \\ R_{f} \\ R_{d1} \end{bmatrix} \begin{bmatrix} i_{d} \\ i_{f} \\ i_{d1} \end{bmatrix} - \begin{bmatrix} \dot{\theta}_{r}\psi_{q} \\ 0 \\ 0 \end{bmatrix} - \frac{d}{dt} \begin{bmatrix} \psi_{d} \\ \psi_{f} \\ \psi_{d1} \end{bmatrix}$$

$$\begin{bmatrix} v_{q} \\ 0 \\ 0 \end{bmatrix} = -\begin{bmatrix} R_{a} \\ R_{q1} \\ R_{q2} \end{bmatrix} \begin{bmatrix} i_{q} \\ i_{q1} \\ i_{q2} \end{bmatrix} + \begin{bmatrix} \dot{\theta}_{r}\psi_{d} \\ 0 \\ 0 \end{bmatrix} - \frac{d}{dt} \begin{bmatrix} \psi_{q} \\ \psi_{q1} \\ \psi_{q2} \end{bmatrix}$$

with the following flux-current relations:

$$\begin{bmatrix} \psi_{d} \\ \psi_{f} \\ \psi_{d_{1}} \end{bmatrix} = \begin{bmatrix} L_{dd} & L_{df} & L_{dd1} \\ L_{df} & L_{ff} & L_{fd1} \\ L_{dd1} & L_{fd1} & L_{d1d1} \end{bmatrix} \begin{bmatrix} i_{d} \\ i_{f} \\ i_{d1} \end{bmatrix}$$
$$\begin{bmatrix} \psi_{q} \\ \psi_{q1} \\ \psi_{q2} \end{bmatrix} = \begin{bmatrix} L_{qq} & L_{qq_{1}} & L_{qq_{2}} \\ L_{qq1} & L_{q1q1} & L_{q1q2} \\ L_{qq2} & L_{q1q2} & L_{q2q2} \end{bmatrix} \begin{bmatrix} i_{q} \\ i_{q1} \\ i_{q2} \end{bmatrix}$$

Energy, power and torque

Balance of power at stator:

$$p_T + p_{Js} + \frac{dW_{ms}}{dt} = p_{r \to s}$$

 p_T : three-phase instantaneous power leaving the stator

 p_{Js} : Joule losses in stator windings

 W_{ms} : magnetic energy stored in the stator windings

 $p_{r\to s}$: power transfer from rotor to stator (mechanical? electrical?)

Three-phase instantaneous power leaving the stator :

$$p_{T}(t) = v_{a}i_{a} + v_{b}i_{b} + v_{c}i_{c} = \mathbf{v}_{T}^{T}\mathbf{i}_{T} = \mathbf{v}_{P}^{T}\mathcal{PP}^{T}\mathbf{i}_{P} = \mathbf{v}_{P}^{T}\mathbf{i}_{P} = v_{d}i_{d} + v_{q}i_{q} + v_{o}i_{o}$$

$$= -\underbrace{\left(R_{a}i_{d}^{2} + R_{a}i_{q}^{2} + R_{a}i_{o}^{2}\right)}_{PJs} - \underbrace{\left(i_{d}\frac{d\psi_{d}}{dt} + i_{q}\frac{d\psi_{q}}{dt} + i_{o}\frac{d\psi_{o}}{dt}\right)}_{dW_{ms}/dt} + \dot{\theta}_{r}\left(\psi_{d}i_{q} - \psi_{q}i_{d}\right)$$

$$\Rightarrow p_{r\to s} = \dot{\theta}_r \left(\psi_d i_q - \psi_q i_d \right)$$

Balance of power at rotor:

$$P_m + p_f = p_{Jr} + \frac{dW_{mr}}{dt} + p_{r \to s} + \frac{dW_c}{dt}$$

 P_m : mechanical power provided by the turbine

 p_f : electrical power provided to the field winding (by the excitation system)

 p_{Jr} : Joule losses in the rotor windings

 W_{mr} : magnetic energy stored in the rotor windings

 W_c : kinetic energy of all rotating masses.

Instantaneous power provided to field winding:

$$p_{f} = v_{f}i_{f} = v_{f}i_{f} + v_{d1}i_{d1} + v_{q1}i_{q1} + v_{q2}i_{q2}$$

$$= \underbrace{(R_{f}i_{f}^{2} + R_{d1}i_{d1}^{2} + R_{q1}i_{q1}^{2} + R_{q2}i_{q2}^{2})}_{PJ_{f}} + \underbrace{i_{f}\frac{d\psi_{f}}{dt} + i_{d1}\frac{d\psi_{d1}}{dt} + i_{q1}\frac{d\psi_{q1}}{dt} + i_{q2}\frac{d\psi_{q2}}{dt}}_{dW_{mr}/dt}$$

$$P_m - \frac{dW_c}{dt} = \dot{\theta_r}(\psi_d i_q - \psi_q i_d)$$

Equation of rotor motion:

$$\mathcal{I}\frac{d^2\theta_r}{dt^2} = T_m - T_e$$

 $\ensuremath{\mathcal{I}}$: moment of inertia of all the rotating masses

 T_m : mechanical torque applied to the rotor by the turbine

 T_e : electromagnetic torque applied to the rotor by the generator.

Multiplying the above equation by $\dot{\theta_r}$:

$$\mathcal{I}\,\dot{\theta_r}\,\ddot{\theta_r}=\dot{\theta_r}T_m-\dot{\theta_r}T_e$$

$$\frac{dW_c}{dt} = P_m - \dot{\theta_r} T_e$$

 P_m : mechanical power provided by the turbine.

Hence, the (compact and elegant !) expression of the electromagnetic torque is:

$$T_e = \psi_d i_q - \psi_q i_d$$

<u>Note</u>. The power transfer $p_{r\to s}$ from rotor to stator is of mechanical nature only.

The various components of the torque $T_{\rm e}$

$$T_e = L_{dd}i_di_q + L_{df}i_fi_q + L_{dd1}i_{d1}i_q - L_{qq}i_qi_d - L_{qq1}i_{q1}i_d - L_{qq2}i_{q2}i_d$$

 $(L_{dd} - L_{qq}) i_d i_q$: synchronous torque due to rotor saliency

- exists in salient-pole machines only
- even without excitation ($i_f = 0$), the rotor tends to align its direct axis with the axis of the rotating magnetic field created by the stator currents, offering to the latter a longer path in iron
- a significant fraction of the total torque in a salient-pole generator.

$L_{dd_1}i_{d1}i_q-L_{qq1}i_{q1}i_d-L_{qq2}i_{q2}i_d$: damping torque

- due to currents induced in the amortisseurs
- zero in steady-state operation.

 $L_{df}i_fi_q$: only component involving the field current i_f

- the main part of the total torque in steady-state operation
- in steady state, it is the synchronous torque due to excitation
- during transients, the field winding also contributes to the damping torque.

The synchronous machine in steady state

- Balanced three-phase currents of angular frequency ω_N flow in the stator windings
- a direct current flows in the field winding subjected to a constant excitation voltage:

$$i_f = \frac{V_f}{R_f}$$

• the rotor rotates at the synchronous speed:

$$\theta_r = \theta_r^o + \omega_N t$$

• no current is induced in the other rotor circuits:

$$i_{d1} = i_{q1} = i_{q2} = 0$$

Operation with stator opened

$$i_a = i_b = i_c = 0$$

 $\Rightarrow i_d = i_q = i_o = 0$
 $\Rightarrow \psi_d = L_{df}i_f \text{ and } \psi_q = 0$

Park equations:

$$\begin{aligned}
 v_d &= 0 \\
 v_q &= \omega_N \psi_d = \omega_N L_{df} i_f
 \end{aligned}$$

Getting back to the stator voltages, e.g. in phase a:

$$v_{a}(t) = \sqrt{\frac{2}{3}}\omega_{N}L_{df}i_{f}\sin(\theta_{r}^{o} + \omega_{N}t) = \sqrt{2}E_{q}\sin(\theta_{r}^{o} + \omega_{N}t)$$

 $E_q = \frac{\omega_N L_{df} I_f}{\sqrt{3}} = \text{e.m.f.}$ proportional to excitation current = RMS voltage at the terminal of the opened machine.

Operation under load

$$\begin{split} v_{a}(t) &= \sqrt{2}V\cos(\omega_{N}t + \theta) \qquad v_{b}(t) = \sqrt{2}V\cos(\omega_{N}t + \theta - \frac{2\pi}{3}) \qquad v_{c}(t) = \sqrt{2}V\cos(\omega_{N}t + \theta + \frac{2\pi}{3}) \\ i_{a}(t) &= \sqrt{2}I\cos(\omega_{N}t + \psi) \qquad i_{b}(t) = \sqrt{2}I\cos(\omega_{N}t + \psi - \frac{2\pi}{3}) \qquad i_{c}(t) = \sqrt{2}I\cos(\omega_{N}t + \psi + \frac{2\pi}{3}) \\ i_{d} &= \sqrt{\frac{2}{3}}\sqrt{2}I\left[\cos(\theta_{r}^{o} + \omega_{N}t)\cos(\omega_{N}t + \psi) + \cos(\theta_{r}^{o} + \omega_{N}t - \frac{2\pi}{3})\cos(\omega_{N}t + \psi - \frac{2\pi}{3}) + \cos(\theta_{r}^{o} + \omega_{N}t + \frac{2\pi}{3})\cos(\omega_{N}t + \psi + \frac{2\pi}{3})\right] \\ &= \frac{I}{\sqrt{3}}[\cos(\theta_{r}^{o} + 2\omega_{N}t + \psi) + \cos(\theta_{r}^{o} + 2\omega_{N}t + \psi - \frac{4\pi}{3}) + \cos(\theta_{r}^{o} + 2\omega_{N}t + \psi + \frac{4\pi}{3}) \\ &+ 3\cos(\theta_{r}^{o} - \psi)\right] = \sqrt{3}I\cos(\theta_{r}^{o} - \psi) \end{split}$$

Similarly:

$$i_q = \sqrt{3}I\sin(\theta_r^o - \psi)$$
 $i_o = 0$
 $v_d = \sqrt{3}V\cos(\theta_r^o - \theta)$ $v_q = \sqrt{3}V\sin(\theta_r^o - \theta)$ $v_o = 0$

In steady-state, i_d and i_q are constant. This was expected !

Magnetic flux in the d and q windings:

$$\psi_d = L_{dd}i_d + L_{df}i_f$$

$$\psi_q = L_{qq}i_q$$

The electromagnetic torque:

$$T_e = \psi_d i_q - \psi_q i_d$$

is constant. This is important from mechanical viewpoint (no vibration !).

Park equations:

$$\begin{array}{rcl} v_d & = & -R_a i_d - \omega_N L_{qq} i_q = -R_a i_d - X_q i_q \\ v_q & = & -R_a i_q + \omega_N L_{dd} i_d + \omega_N L_{df} i_f = -R_a i_q + X_d i_d + \sqrt{3} E_q \\ v_o & = & 0 \end{array}$$

 $X_d = \omega_N L_{dd}$: direct-axis synchronous reactance $X_a = \omega_N L_{aa}$: quadrature-axis synchronous reactance


Phasor diagram

The Park equations become:

$$V\cos(\theta_r^o - \theta) = -R_aI\cos(\theta_r^o - \psi) - X_qI\sin(\theta_r^o - \psi)$$

$$V\sin(\theta_r^o - \theta) = -R_aI\sin(\theta_r^o - \psi) + X_dI\cos(\theta_r^o - \psi) + E_q$$


which are the projections on the d and q axes of the complex equation:



Particular case: round-rotor machine:


$$X_d = X_q = X$$

$$\bar{E}_q = \bar{V} + R_a \bar{I} + jX(\bar{I}_d + \bar{I}_q) = \bar{V} + R_a \bar{I} + jX\bar{I}$$



Such an equivalent circuit cannot be derived for a salient-pole generator.

Powers



$$\bar{E}_q = E_q e^{j(\theta_r^o - \frac{\pi}{2})}$$

$$\bar{I}_d = I\cos(\theta_r^o - \psi)e^{j\theta_r^o} = \frac{i_d}{\sqrt{3}}e^{j\theta_r^o}$$

$$\bar{I} = \bar{I}_d + \bar{I}_q = (\frac{i_d}{\sqrt{3}} - j\frac{i_q}{\sqrt{3}})e^{j\theta_r^o}$$

$$\bar{V}_d = V \cos(\theta_r^o - \theta) e^{j\theta_r^o} = \frac{v_d}{\sqrt{3}} e^{j\theta_r^o}$$

$$ar{V} = ar{V}_d + ar{V}_q = (rac{V_d}{\sqrt{3}} - jrac{V_q}{\sqrt{3}})e^{j heta_r^o}$$

$$\bar{I}_q = I \sin(\theta_r^o - \psi) e^{j(\theta_r^o - \frac{\pi}{2})} = -j \frac{i_q}{\sqrt{3}} e^{j\theta_r^o}$$

 $\bar{V}_q = V \sin(\theta_r^o - \theta) e^{j(\theta_r^o - \frac{\pi}{2})} = -j \frac{v_q}{\sqrt{3}} e^{j\theta_r^o}$

Three-phase complex power produced by the machine:

$$S = 3\bar{V}\bar{I}^* = 3\left(\frac{v_d}{\sqrt{3}} - j\frac{v_q}{\sqrt{3}}\right)\left(\frac{i_d}{\sqrt{3}} + j\frac{i_q}{\sqrt{3}}\right) = (v_d - jv_q)(i_d + ji_q)$$

$$\Rightarrow P = v_d i_d + v_q i_q \qquad Q = v_d i_q - v_q i_d$$

P and Q as functions of V, E_q and the internal angle δ , assuming $R_a \simeq 0$?

$$v_d = -X_q i_q \Rightarrow i_q = -\frac{v_d}{X_q}$$

$$v_q = X_d i_d + \sqrt{3} E_q \Rightarrow i_d = \frac{v_q - \sqrt{3} E_q}{X_d}$$

$$v_d = \sqrt{3} V \cos(\theta_r^o - \theta) = -\sqrt{3} V \sin \delta$$

$$v_q = \sqrt{3} V \sin(\theta_r^o - \theta) = \sqrt{3} V \cos \delta$$

$$P=3\frac{E_qV}{X_d}\sin\delta+\frac{3V^2}{2}(\frac{1}{X_q}-\frac{1}{X_d})\sin2\delta \qquad Q=3\frac{E_qV}{X_d}\cos\delta-3V^2(\frac{\sin^2\delta}{X_q}+\frac{\cos^2\delta}{X_d})$$

Case of a round-rotor machine: $P = 3\frac{E_q V}{X} \sin \delta$ $Q = 3\frac{E_q V}{X} \cos \delta - 3\frac{V^2}{X}$

Nominal values, per unit system and orders of magnitudes

Stator

- nominal voltage U_N : voltage for which the machine has been designed (in particular its insulation).
 - The real voltage may deviate from this value by a few %
- nominal current I_N: current for which machine has been designed (in particular the cross-section of its conductors).
 Maximum current that can be accepted without limit in time
- nominal apparent power: $S_N = \sqrt{3}U_N I_N$.

Conversion of parameters in per unit values:

- base power: $S_B = S_N$
- base voltage: $V_B = U_N/\sqrt{3}$
- base current: $I_B = S_N/3V_B$
- base impedance: $Z_B = 3V_B^2/S_B$.

Orders of magnitude

(more typical of machines with a nominal power above 100 MVA) (pu values on the machine base)

	round-rotor	salient-pole
	machines	machines
resistance R_a	0.005 pu	
direct-axis reactance X_d	1.5 - 2.5 pu	0.9 - 1.5 pu
quadrature-axis reactance X_q	1.5 - 2.5 pu	0.5 - 1.1 pu

Park (equivalent) windings

base power:

 S_N

• base voltage: $\sqrt{3}V_R$

• base current:

$$\frac{S_N}{\sqrt{3}V_B} = \sqrt{3}I_B \qquad \text{(single-phase formula !)}$$

With this choice:

$$i_{dpu} = \frac{i_d}{\sqrt{3}I_B} = \frac{\sqrt{3}}{\sqrt{3}}\frac{I}{I_B}\cos(\theta_r^{\circ} - \psi) = I_{pu}\cos(\theta_r^{\circ} - \psi)$$

Similarly:

$$\begin{split} i_{qpu} &= I_{pu} \sin(\theta^o_r - \psi) \qquad v_{dpu} = V_{pu} \cos(\theta^o_r - \theta) \qquad v_{qpu} = V_{pu} \sin(\theta^o_r - \theta) \\ \bar{I} &= \bar{I}_d + \bar{I}_q = (i_d - j \ i_q) e^{j\theta^o_r} \qquad \bar{V} = \bar{V}_d + \bar{V}_q = (v_d - j \ v_q) e^{j\theta^o_r} \end{split}$$

- All coefficients $\sqrt{3}$ have disappeared
- hence, the Park currents (resp. voltages) are exactly the projections on the machine d and g axes of the phasor I (resp. V)